

coudes

Désignation	A×B	C	D	E	F
ABF 00 CO	2×4	10	11	26	16
ABF 0 CO	4×6	14	14	35	20
ABF 0P CO	4×8	14	15	36	21
ABF 1P CO	6×10	22	22	49	28
ABF 1 CO	8×13	24	25	62	38
ABF 2 CO	12×17	29	29	68	43
ABF 3 CO	15×21	32	26	81	50
ABF 4 CO	20×27	38	32	101	60
ABF 5 CO	26×34	50	42	110	62
ABF 6 CO	33×42	67	48	135	90
ABF 7 CO	40×49	67	56	149	100
ABF 8 CO	50×60	88	61	172	110

